

CERTIFICATE OF COMPLIANCE

Certificate Number 20150827-E232353
Report Reference E232353-20031003
Issue Date 2015-AUGUST-27

Issued to: ZHEJIANG CHINT ELECTRICS CO LTD
CHINT INDUSTRIAL ZONE
WENZHOU
ZHEJIANG 325604 CHINA

This is to certify that representative samples of MOTOR CONTROLLERS, MANUAL
See next page for models.


Have been investigated by UL in accordance with the Standard(s) indicated on this Certificate.

Standard(s) for Safety: UL 60947-4-1, Low-Voltage Switchgear and Controlgear
CAN/CSA C22.2 NO 60947-4-1-07, Low-Voltage Switchgear and Controlgear

Additional Information: See the UL Online Certifications Directory at www.ul.com/database for additional information

Only those products bearing the UL Certification Mark should be considered as being covered by UL's Certification and Follow-Up Service.

Look for the UL Certification Mark on the product.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>



CERTIFICATE OF COMPLIANCE

Certificate Number 20150827-E232353
Report Reference E232353-20031003
Issue Date 2015-AUGUST-27

This is to certify that representative samples of the product as specified on this certificate were tested according to the current UL requirements.

"Open Type", Manual Motor Controllers, AC Motor Starter: Model NS followed by 2, followed by 25 or 25X, followed by 0.16, 0.25, 0.4, 0.63, 1, 1.6, 2.5, 4, 6.3, 10, 14, 18, 23, 25.

Polymeric Enclosure for manual motor controllers, Model NS2-MC, NS2-MC01, and WPB-1


Listed Accessories:

Under-voltage release: Model NS2, followed by UV, followed by 110, 220 or 380.

Shunt Release: Model NS2, followed by SH, followed by 110, 220 or 380.

Transient Auxiliary Contact Group: Model NS2, followed by AE or AU, followed by 11 or 20.

Fault Signal Auxiliary Contact Group: Model NS2, followed by FA, followed by 0110, 0101, 1010, or 1001.



Bruce Mahrenholz, Director North American Certification Program

UL LLC

Any information and documentation involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL. For questions, please contact a local UL Customer Service Representative at <http://ul.com/aboutul/locations/>

